

City of San Jacinto

April 2021 City Manager Update – May 18, 2021

Department Overview

	February 2021	March 2021	April 2021	2021 Totals	2020 Totals
Phone Calls	1,669	2,042	2,113	7,316	16,102
Counter Visits	**	**	**	**	1,908
Total Customer Contacts	1,669	2,042	2,113	7,316	18,010



^{**}No Counter visits due to City Hall Closure in response to COVID-19

Planning Division

	April 2021	2021 Totals	2020 Totals
Entitlements Submitted	9	38	83
Projects Approved	4	11	64
Over the Counter (Temporary Use Permit, Special Event Permit, Home Occupation Permit)	10	40	71



Planning Division





Canopy to be supplied and installed by Dollar Tree's sign vendor






Building & Safety Division

	February 2021	March 2021	April 2021	2021 Totals	2020 Totals
Building Inspections	343	408	521	1,199	3,845
Permits Issued	106	88	78	280	1,077
Permits Applied For	113	154	168	360	1,341
Private Investment	\$3.245M	\$1.238M	\$2.765M	\$13.204M	\$43.343M



Building & Safety Division


New Single-Family Residences "Finaled"		
2021	55*	
2020	141	
2019	211	
2018	375	
2017	235	






Demler Egg Ranch Footings Inspection & Slab 1 Progress








DR Horton – Pheasant Pointe Final Inspections







Residential Pool – Final Inspection







Richmond American Homes Seasons at Potter Ranch – Insulation Inspection







Code Enforcement Division

Issues	February 2021	March 2021	April 2021	2021 Totals	2020 Totals	2019 Totals
Notice of Violation Issued	429	638	675	1,966	6,479	7,069
Citations Issued	38	37	46	144	575	1,068
Proactive Activities	440	576	578	1,813	6,995	8,451
New Inspections	112	169	127	523	1,525	1,624
Re-Check Inspections	475	571	680	2,046	6,317	6,981
Cases Closed	242	330	418	1,155	3,945	4,564
Totals	1,736	2,321	2,524	2,802	25,836	29,75

2019 Totals	2018 Totals
7,069	7,081
1,068	994
8,451	8,613
1,624	1,618
6,981	7,078
4,564	4,452
29,757	29,836



Overgrown Vegetation







Overgrown Vegetation







Trailer Storage







Wrecked Inoperative Vehicle







Department of Public Utilities - Streets Division

Asphalt Patching Material Purchased

Year to Date

19.5 tons








On Old Mountain

Street maintenance crews removed yard sale signs, picked up roadside debris, palm fronds, tumbleweeds, tree branches, and shopping carts from all areas of the City







Sanderson Ave at Cottonwood Ave





On Meridian Street



Department of Public Utilities - Streets Division















Grind and Overlay – North end of Buena Vista





Remove and Replace – 612 Salam Place




Asphalt Maintenance crew temporarily repaired 160 square feet of pothole material at various street locations

Streets Section also oversaw 2 asphalt jobs by NPG totaling 5342 square feet

Department of Public Utilities – Parks Division - Graffiti Removal

Month	Locations
All 2020	717
January	43
February	81
March	114
April	68
2021 Total	306







Idyllwild Drive and San Jacinto








Department of Public Utilities - Parks Division





New Playground Mulch at the Cutting and Caseros Parks





Landscape Enhancements completed at the Luz Del Sol entry feature



Department of Public Utilities - Storm Water Division

Jetting & Debris Report - APRIL 2021

Linear Feet hydro-jetted

1100LF

Cubic Yards of debris removed from storm


pipelines

72CY

















Clearing the Sanderson Avenue Channel of accumulated weeds trash and debris

Department of Public Utilities – Water Division

APRIL 2021			
Meter Leaks	77		
Meter Readings	4370		
Meters Repaired	14		
Valve Turnings	41		
Meters Installed	9		
Dig Alerts Responses	82		



Production Crew installing an new airvacuum relief valve at the Grand Well



Production Crew preparing to take water quality samples from the sample station on Ramona Boulevard



Construction Crew prepares to make repairs to a service line leak



Department of Public Utilities - Waste Water Division

APRIL 2021				
Miles of sewer lines cleaned	4.87			
Miles of sewer lines videoed & inspected	1.02			






Department of Public Utilities - Waste Water Division



ACINTO



Waste Water, Storm Water and Street Crews filled and repaired a sink hole in the Meadowbrook I subdivision on Grassy Meadows Drive and Sweet Clover Loop









Contractor and Wastewater crews removed sewer blockage left by the original contractor that caused high sewer flow levels on Cherry Laurel Lane in the Tamarisk subdivision